

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/22/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S04UU1017MH

Test ID: D1032-031023

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S04UU1017MH
0			Water Level	
97.59999847	02		Tap Factory	From 5115 Fordleigh
97.59999847			Dye Test Visible	@ TF - cleanout
97.59999847			Dye Test Visible	@ TF - downspout
97.59999847			End of Survey	DYE FLOOD COMPLETED
97.59999847			Manhole	S04UU1014MH